



Office: Copenhagen

Date: 09 December 2009

This certificate is issued to **RONSTAN Danmark Aps, Karetmagervej 23, DK-7100 Vejle**

RONSTAN Danmark ApS

To certify that the undersigned surveyor to Lloyd's Register EMEA did, at their request attended their premises for the purpose of witnessing and testing the following .

Rail System Type S22

The rail system checked against the drawings: Certified Rail System and S22 Car Body Blanck.

The item was subject to a test as stated in DS / EN 795 and test performed with satisfactory result. Items checked after test, and as far as could be seen, free from defect

ID mark.: None applied.

Valid Calibration status of test equipment verified

Kaj Overgaard
Surveyor to Lloyd's Register EMEA

A member of the Lloyd's Register Group



Lloyd's Register, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as the 'Lloyd's Register Group'. The Lloyd's Register Group assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register Group entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.